

VISUAL BUYER'S PACK

2019 CATERPILLAR 966L

Wheel Loader

Reference VBP-000-15 · Documented 29 October 2026

Asset Information

MANUFACTURER Caterpillar	MODEL 966L	YEAR 2019
HOUR METER 14,646 hrs	SERIAL / PIN CAT***1554	

Asset Overview


Front Right Perspective


Rear Left Perspective


Front Left Perspective


Full Right Side


Full Left Side


Full Rear



Full Front

Operator Cab



Hour Meter / Odometer



Instrument Panel



Operator Seat



Cab Interior



Cab Exterior

Engine Compartment

Visual documentation only. No mechanical inspection has been performed unless specifically stated.



Overall Engine Compartment

Hydraulics / Working Components

Visual documentation only. No mechanical inspection has been performed unless specifically stated.



Hydraulic Hoses



Hydraulic Cylinders

Tyres / Tracks / Undercarriage



Tread & Sidewalls



Rear Right Tyre



Front Right Tyre



Front Left Tyre

Identification



Manufacturer Plate

Visual Documentation Notice

This Visual Buyer's Pack has been prepared to provide potential buyers with a structured photographic and visual record of the asset at the time the photographs and recordings were made. RMG does not provide a mechanical, electrical, engineering, safety or technical inspection unless specifically stated in writing. Visual observations are descriptive only and must not be interpreted as professional diagnoses or guarantees regarding the condition, functionality or future performance of the asset. Buyers are encouraged to conduct their own inspection and make independent enquiries before bidding. Assets are sold in accordance with the applicable auction terms and conditions.