

VISUAL BUYER'S PACK

2026 HYUNDAI R215L

Excavator

Reference VBP-000-23 · Documented 2 November 2026

Asset Information

MANUFACTURER	MODEL	YEAR
HYUNDAI	R215L	2026
HOUR METER	**SERIAL / PIN**	
4 hrs	HYN***0973	

Asset Overview


Front Right Perspective



Rear Right Perspective



Rear Left Perspective



Full Front



Front Left Perspective



Full Right Side



Full Left Side



Full Rear

Operator Cab


Hour Meter / Odometer


Instrument Panel


Dashboard



Cab Exterior

Engine Compartment

Visual documentation only. No mechanical inspection has been performed unless specifically stated.


Overall Engine Compartment

Hydraulics / Working Components

Visual documentation only. No mechanical inspection has been performed unless specifically stated.


Hydraulic Cylinders

Tyres / Tracks / Undercarriage



Undercarriage


Sprockets & Idlers


Rollers


Track Pads


Right Track


Left Track

Identification



Engine Number



Serial / PIN



Manufacturer Plate

Visual Documentation Notice

This Visual Buyer's Pack has been prepared to provide potential buyers with a structured photographic and visual record of the asset at the time the photographs and recordings were made. RMG does not provide a mechanical, electrical, engineering, safety or technical inspection unless specifically stated in writing. Visual observations are descriptive only and must not be interpreted as professional diagnoses or guarantees regarding the condition, functionality or future performance of the asset. Buyers are encouraged to conduct their own inspection and make independent enquiries before bidding. Assets are sold in accordance with the applicable auction terms and conditions.