

VISUAL BUYER'S PACK

2018 KOMATSU HM400-3R

Komatsu HM400-3R / Articulated Dump Truck

Reference VBP-000-30 · Documented 6 November 2026

Asset Information

YEAR OF MANUFACTURE

2018

Overall Condition & Angles



Rear elevation



Full side profile, left



Full side profile, right



Front 3/4 view




Rear 3/4 view



Front elevation

Machine Identification & Plates




Hours meter / odometer



Engine & machine data plate

Body Interior & Floor


Inside body: top lip and mount points


Inside body: floor condition

Articulation Joint & Frame


Frame and welds: rear area


Rubber mounting pads: under body


Frame and welds: articulation point


Articulation joint: close-up of pin and bushing


Articulation joint: side view

Tyres & Suspension


Tyre sidewalls: damage or repairs


Rear axle tyres: tread depth and condition


Front tyres: tread depth and condition


All tyres: full view (both sides)


All tyres: full view (both sides)


All tyres: full view (both sides)



All tyres: full view (both sides)



All tyres: full view (both sides)



All tyres: full view (both sides)



All tyres: full view (both sides)

Fitted Extras & Features



Body liner: interior lining or coating



Rear-view camera: screen in cab



A/C cab: exterior and interior unit visible

Visual Documentation Notice
This Visual Buyer's Pack has been prepared to provide potential buyers with a structured photographic and visual record of the asset at the time the photographs and recordings were made. RMG does not provide a mechanical, electrical, engineering, safety or technical inspection unless specifically stated in writing. Visual observations are descriptive only and must not be interpreted as professional diagnoses or guarantees regarding the condition, functionality or future performance of the asset. Buyers are encouraged to conduct their own inspection and make independent enquiries before bidding. Assets are sold in accordance with the applicable auction terms and conditions.