

VISUAL BUYER'S PACK

2018 KOMATSU HM400-3R

Komatsu HM400-3R Articulated Dump Truck

Reference VBP-000-31 · Documented 10 November 2026

Asset Information

YEAR OF MANUFACTURE

2018

Overall Condition & Angles



Full side profile, right



Rear elevation



Front elevation



Rear 3/4 view



Front 3/4 view



Full side profile, left

Machine Identification & Plates



Hours meter / odometer



Engine & machine data plate

Body Interior & Floor


Inside body: top lip and mount points


Inside body: side wall condition (right)


Inside body: floor condition


Inside body: side wall condition (right)


Inside body: side wall condition (right)


Inside body: side wall condition (right)


Inside body: side wall condition (right)


Inside body: side wall condition (right)

Articulation Joint & Frame


Rubber mounting pads: under body



Frame and welds: rear area


Frame and welds: articulation point


Articulation joint: close-up of pin and bushing


Articulation joint: side view

Tyres & Suspension



Tyre sidewalls: damage or repairs



Rear axle tyres: tread depth and condition



Front tyres: tread depth and condition

Fitted Extras & Features



Auto lube system: lines or pump visible



Rear-view camera: screen in cab

Visual Documentation Notice

This Visual Buyer's Pack has been prepared to provide potential buyers with a structured photographic and visual record of the asset at the time the photographs and recordings were made. RMG does not provide a mechanical, electrical, engineering, safety or technical inspection unless specifically stated in writing. Visual observations are descriptive only and must not be interpreted as professional diagnoses or guarantees regarding the condition, functionality or future performance of the asset. Buyers are encouraged to conduct their own inspection and make independent enquiries before bidding. Assets are sold in accordance with the applicable auction terms and conditions.